



# Phase Rotation Indicator



**Fluke 9062**

## Fluke 9062 Motor and Phase Rotation Indicator

### Product highlights

- 3 phase indication
- Indication of phase rotation
- Indication of motor rotation direction
- Contact free determination of the rotation direction of running motors
- 2 years warranty



Fluke 9062

### Take the guesswork out of phase / motor rotation measurements

The unique Fluke 9062 provides rotary field and motor rotation indication with the benefits of contact-less detection. Purpose made for commercial and industrial environments, the Fluke 9062 provides rapid indication of 3 phase rotation using test leads supplied or can be used to determine motor rotation on synchronous and asynchronous 3 phase motors. The contact-less detection is ideal for use on motors where the shaft is not visible. Test probes supplied with the instrument have a variable clamping range for safe contact, especially in industrial sockets.

### Features

	9062
3 phase indication	Via LED
Indication of phase rotation	•
Indication of motor rotation direction	•
Contact free determination of the rotation direction of running motors	•

### Specifications

	9062
Voltage range	Up to 400 V AC
Phase display	120 - 400 V AC
Frequency range	2-400 Hz
Operating time	Continuous



### Fluke 9062 Applications



Determine the presence of phase sequence of multiphase electrical supplies.



Determine the rotation of running motors simply by placing the instrument on the motor casing.



Check the correct rotation of motors prior to connection.





## CONTACT DETAIL



[tasira@rediffmail.com](mailto:tasira@rediffmail.com)



2522 8205, 2523 1145



#293, (Old 142)  
Linghi Chetty Street,  
Chennai-600 001



[www.tasirainstrumentations.com](http://www.tasirainstrumentations.com)